


Measurement campaign

Backed by years' radio expertise, Siradel's tracks are over 4 continents. CW or SCAN Measurements for different prevailing technologies are realized. Here are main steps of technical project management:

STAGE 0 - Definition

- Select representative area for model tuning
- Define routes for model tuning
- Check all administrative authorisations
- Select the free frequency channel




STAGE 1 - Preparation

- Kick off meeting
- Select sites
- Design the drive tests
- Make health and safety visits




STAGE 2 - Measurement collection

- On-site management control
- Acquisition of the raw data
- TX/RX quality check after measurement
- Validation of measurement for model tuning
- Control of collected measurement data



STAGE 3 - Post processing

- Filter out badly-located bins
- Filter fast-fading
- Filter out noise-affected bins



SIRADEL's R&D team is the strong backup throughout entire measurement!

SIRADEL SAS

Tel: +33 (0) 223 48 05 00 - Fax: +33 (0) 223 48 05 99
E-mail: info@siradel.com - www.siradel.com